

Bldg #8 - Blacksmith Shop - 1916

Element	Material	Condition	Performance Requirement	Proposed Treatment
1 Floor	Concrete slab (1924 & 31 Sanborns indicates dirt floor.)	Good		
2 Tracks	One track down center			
3 Walls	Un-reinforced brick with lime mortar. Steel arches are engaged in masonry.	No cracking. Mortar in generally good condition.		Lightly clean with water, but retain patina. Vestibule structures being added at north and south ends.
4 Windows	Steel sash with wire reinforced translucent glass. 1-1/4" rabbet on frames.	Majority of glass on east (track) side has been replaced with fiberglass panels.		Retain. Clean, remove rust, re-glaze with insulated glass and repaint. The glazing compound contains asbestos and will have to be abated.
5 Roof Structure	Steel arches with wood deck (1931 Sanborn indicates wood trusses.)	Wood deck appears to be in generally good condition.		
6 Heating	Gas radiant			Remove.